

ZAŁĄCZNIK – DOKUMENTACJA FOTOGRAFICZNA



Fot. 1.



Fot. 2




Fot. 3



Fot. 4



Fot. 5



Fot. 6



Fot. 7




Fot. 8




Fot. 9



Fot. 10



Fot. 11



Fot. 12



Fot. 13



Fot. 14



Fot. 15



Fot. 16



Fot. 17




Fot. 18



Fot. 19



Fot. 20



Fot. 21




Fot. 22




Fot. 23



Fot. 24



Fot. 25



Fot. 26



Fot. 27



Fot. 28




Fot. 29



Fot. 30



Fot. 31



Fot. 32



Fot. 33



Fot. 34




Fot. 35



Fot. 36



Fot. 37



Fot. 38



Fot. 39

Fot. 40

Fot. 41



Fot. 42



Fot. 43

**Naprawa pokrycia - odpylacza przy
kominie stalowym**

